



NASCO-OP

IDEAL FOR

- Motor Connections
- Testing Equipment
- Air Compressors
- Portable Machinery
- Lifting Magnets
- Welding Machines
- Battery Chargers
- Tap Chargers


AND MORE!

Push and Twist - LOCKED

Twist and Pull - RELEASED

Hunter single pole solderless electric cable connectors are almost as fast as a telephone jack.

Mate and twist – you're locked for power. Reverse twist and pull – you're disconnected.



<u>Broad Contact Surface – Ample Copper Cross Section</u> - Achieve high electrical conductivity and a good factor of safety for heavy current demands and high intermittent overloads.

<u>High Pressure Contact - No Springs</u> - Contact surfaces are conditioned automatically by the twist and push action of connecting.

<u>Well Insulated – Non-Skid Rubber Grips</u>: Insulated thick molded rubber, oil and grease resistant, cushioned and protected internal parts.

Quick and Easy Installation - On Site Install - A screwdriver and knife are the only tools required to install cables. Eliminate soldering, crimping, taping, use of bolts, nuts, washers and terminal lugs! Connected cables will not loosen or pull out under strain or vibrations.

<u>Built to Last - Rugged Construction</u> - No breakable plastic or other composition parts. No springs or delicate parts to fail or replace. Hunter Connectors withstand punishment or rough handling, dragging, compression load and impact.

RATING	PART	PART NO.	OVERALL LENGTH	O.D. OVER RUBBER GRIP	MAXIMUM WIRE SIZE (dia. Of bared wire)
200 Amperes	Connector Complete	200M & 200F	7-1/2"	1-3/8"	7/16"4375"
200 Amperes	Plug Only	200M	5-1/16"	1-3/8"	7/16"4375"
200 Amperes	Receptacle Only	200F	3-3/4"	1-3/8"	7/16"4375"
400 Amperes	Connector Complete	400M & 400F	7-1/2"	1-5/8"	9/16"5625"
400 Amperes	Plug Only	400M	5-3/16"	1-5/8"	9/16"5625"
400 Amperes	Receptacle Only	400F	3-3/4"	1-5/8"	9/16"5625"





